

REPUBLIC OF ALBANIA



ALBANIAN CIVIL AVIATION AUTHORITY

AIRWORTHINESS DIRECTIVE

ACAA-DFS-AD-No.003

Issue: 01, Revision 00

Date: 12.07.2024

Approved by Shirt Shirt

Executive Director of Albanian Civil Aviation Authority



0.1 Record of Amendments

The table below describes the dates and reason for the different amendments of the current procedure. A vertical black line on the left-hand side of the page identify the changes with the previous version.

0.2 Revision table

Page #.	Issue No.	Revision No.	Date	Edited by

Issue: 01, Revision 00 Page: 2 from 4

Date: 12.07.2024



1. Name of the AD:

EASA AD No. 2024-0030, ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 3 – Certification Maintenance Requirements – Amendment

2. Full Description of the AD:

This AD addresses Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 3 – Certification Maintenance Requirements – Amendment for Airbus A318, A319, A320, and A321 aeroplanes. It requires compliance with new and/or more restrictive maintenance tasks specified in the ALS (Airworthiness Limitations Section) Part 3 Revision 09.

3. Issued and Effective Dates:

Issued: 31 January 2024 Effective: 14 February 2024

4. Full List of Aircraft Affected:

Airbus A318-111, A318-112, A318-121, A318-122

Airbus A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A319-171N

Airbus A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N

Airbus A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252NX, A321-252NX, A321-253NX, A321-271NX, A321-272NX.

5. Description of How It Can Be Resolved:

The AD mandates accomplishment of all applicable maintenance tasks as per the revised ALS Part 3 within specified compliance times, and corrective actions if discrepancies are found during maintenance checks.

Manufacturer: Airbus S.A.S. TCDS Number: EASA.A.064

Supersedure: This AD supersedes EASA AD 2022-0091 and EASA AD 2023-0138.

ATA Chapter: ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 3 – Certification Maintenance Requirements – Amendment

Certification Maintenance Nequirements – Amendment

For detailed instructions on compliance and specific actions required, please refer to the complete AD document or contact Airbus's Airworthiness Office for technical inquiries.

For full compliance please refer to:

https://ad.easa.europa.eu/blob/EASA AD 2024 0030.pdf/AD 2024-0030 1

Issue: 01, Revision 00 Page: 3 from 4

Date: 12.07.2024